

Fig. 1 Various cuts in quartz crystal




Fig. 2 Temperature coefficient versus cutting angle  $\theta$  of plate